



Solving environment-related business problems worldwide

www.deltaenv.com

27141 Aliso Creek Road • Suite 270
Aliso Viejo, California 92656 USA

949.362.3077 800.477.7411
Fax 949.362.0290

April 14, 2005

Ms. Betti MacGregor
San Bernardino County Fire Dept.
Hazardous Materials Division
620 South E Street
San Bernardino, California 92415

Sent by UPS

Subject: Quarterly Update Report Submittal

Dear Ms. MacGregor:

On behalf of Atlantic Richfield Company, Delta Environmental Consultants, Inc. is submitting the enclosed Quarterly Site Status Report for the First Quarter 2005. The enclosed quarterly report was prepared for the following ARCO Facility:

ARCO Facility No.

3081

SBCFD Case No.

93056

Location

12201 Mountain Avenue, Chino

If you have any questions, please contact the undersigned at (949) 860-0212.

Sincerely,

DELTA ENVIRONMENTAL CONSULTANTS, INC.

A handwritten signature in black ink, appearing to read "Paul N. McCarter", is written over a horizontal line.

Paul N. McCarter, R.G.
Project Manager

4-14-05
Date

Enclosure: Atlantic Richfield Company Quarterly Update Report

cc: Mr. Gordon Terhune, Atlantic Richfield Company, La Palma, California

**ATLANTIC RICHFIELD COMPANY QUARTERLY SITE STATUS REPORT
FIRST QUARTER 2005
APRIL 30, 2005**

Facility No.: 3081 Address: 12201 Mountain Avenue, Chino, California
Atlantic Richfield Company Environmental Business Gordon Terhune / (562) 438-3871
Manager / Phone No.:
Consulting Co. / Contact Person/Phone No.: Delta Environmental / Paul McCarter (949) 860-0212
Primary Agency / Contact Person/Regulatory ID No.: County of San Bernardino Fire Department (SBCFD) /
Ms. Betti MacGregor / Case No. 93056
Other Agencies to Receive Copies: NA

WORK PERFORMED THIS QUARTER (First - 2005):

1. Submitted Quarterly Site Status Report.
2. Performed construction and electrical upgrades to soil-vapor extraction (SVE) system.

WORK PROPOSED FOR THE NEXT QUARTER (Second - 2005):

1. Submit Quarterly Site Status Report.
2. Obtain remaining permits from the City of Chino.
3. Upon final inspection, review, and release by the City of Chino, connection of electrical power to SVE system by Southern California Edison to remediation system, and startup of SVE system.
4. Perform weekly operation and maintenance of the SVE system.


Current Phase of Project:	<u>Remediation</u>		
Frequency of Sampling:	<u>NA</u>		
Frequency of Monitoring:	<u>NA</u>		
Permits for Discharge (No.):	<u>None</u>		
Approx. Depth to Groundwater:	<u>70 feet</u>	Measured	Estimated <u>X</u>
Groundwater Gradient:	<u>NA</u>	(Magnitude)	<u>East</u> (Direction)

ATTACHMENTS: Figure 1 - Site Location Map
Figure 2 - Site Map


If you have any questions or comments concerning this correspondence, please contact Paul McCarter (949) 860-0212.

Reported and signed by,

DELTA ENVIRONMENTAL CONSULTANTS, INC.


Paul N. McCarter
Project Manager

4-14-05
Date



GENERAL NOTES:

BASE MAP FROM U.S.G.S. 1967
 ONTARIO QUADRANGLE
 CHINO, CA
 7.5 MINUTE TOPOGRAPHIC MAP
 PHOTOREVISED 1981




FIGURE 1
SITE LOCATION MAP
 ARCO FACILITY NO. 3081
 12201 MOUNTAIN AVENUE
 CHINO, CA

PROJECT NO. AM00-807	DRAWN BY
FILE NO. SLM 1	PREPARED BY C. OTA
DATE 6/24/02	REV. REVIEWED BY






FIGURE 2

SITE MAP
ARCO FACILITY NO. 3081
12201 MOUNTAIN AVENUE
CHINO, CA.

PROJECT NO. AM00-807	DRAWN BY
FILE NO. A0-807-01	PREPARED BY A. BAIRD
DATE 19 JUN 02	REV. 0
	REVIEWED BY



LEGEND

- BC-1 VADOSE MONITORING WELL (BROWN AND CALDWELL, 6/95)
- SOIL BORING LOCATIONS (W.W. IRWIN, 8/93)
- SOIL BORING LOCATIONS (W.W. IRWIN, 5/94)
- VAPOR EXTRACTION WELL LOCATIONS (W.W. IRWIN, 5/94)